

BD-05T067LM Wiring Instructions

1	PWM speed control	Blue	10-30KHz; 10-100% (100% = max. rpm / 0-10% = 0 rpm); Low: min 0V / max. 0.5V High: min. 2V / max. 5.5V Connect to black wire full speed
2	Power Supply Negative Pole GND	Black	GROUND
3	RPM feedback FG	Yellow	Output, signal current 2 mA 5 pulses / cycle Low: min. 0V / max. 0.5V High: min. 2V / max. 5.5V
4	Power Supply Positive Pole VCC	Red	24V